




TACAN Y RWY 34

|                         |                    |                         |                               |                                       |
|-------------------------|--------------------|-------------------------|-------------------------------|---------------------------------------|
| TACAN<br>Chan <b>73</b> | NBS<br><b>345°</b> | APCH CRS<br><b>345°</b> | Rwy Idg<br>TDZE<br>Arprt Elev | <b>6002</b><br><b>21</b><br><b>23</b> |
|-------------------------|--------------------|-------------------------|-------------------------------|---------------------------------------|

AL-767 [USN]

BARKING SANDS PMRF (PHBK)

|                                          |                               |                               |                                                                                    |                        |
|------------------------------------------|-------------------------------|-------------------------------|------------------------------------------------------------------------------------|------------------------|
| *Circling not authorized E of Rwy 16-34. |                               |                               | MISSED APPROACH: Climbing left turn to 3000 on NBS TACAN R-222 to DIKINY and hold. |                        |
| ATIS ★<br><b>128.0</b>                   | HCF APP<br><b>126.5 269.4</b> | TOWER ★<br><b>126.2 360.2</b> | GND CON ★<br><b>124.2 340.2</b>                                                    | UNICOM<br><b>122.8</b> |



TACAN Y RWY 34