




|                                       |                        |                             |  |
|---------------------------------------|------------------------|-----------------------------|--|
| VORTAC RQZ<br><b>112.2</b><br>Chan 59 | APP CRS<br><b>043°</b> | Rwy Idg<br>TDZE<br>Apt Elev | <b>N/A</b><br><b>N/A</b><br><b>764</b> |
|---------------------------------------|------------------------|-----------------------------|--|

**VOR-B**

HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)

|               |  |   |  |
|---------------|--|---|--|
| DME required. |  | MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold. |  |
|---------------|--|---|--|

|                          |   |                       |                                 |
|--------------------------|---|-----------------------|---------------------------------|
| AWOS-3PT<br><b>120.0</b> | HUNTSVILLE APP CON★<br><b>125.6 354.1</b> | GCO<br><b>121.725</b> | UNICOM<br><b>123.0 (CTAF) 0</b> |
|--------------------------|---|-----------------------|---------------------------------|



| CATEGORY          | A      | B           | C                       | D                       |
|-------------------|--------|-------------|-------------------------|-------------------------|
| <b>C</b> CIRCLING | 1500-1 | 736 (800-1) | 1560-2¼<br>796 (800-2¼) | 2000-3<br>1236 (1300-3) |

**VOR-B**

SE-4, 15 MAY 2025 to 12 JUN 2025

SE-4, 15 MAY 2025 to 12 JUN 2025